

Notes on Car Wrapping Films



„End of Roll“ – Mark Phenomenon / Storage Stains – „Blushing“

Dear customers,


in certain circumstances slight stains and/or blushing as well as marks at the end of the roll can occur when working with diverse car wrapping films. These phenomena can also occur when working with commissioned products.

Generally, this does not represent a reason for complaint and can be removed while cutting the material or during its application.


With the help of the products described below, the following methods lead to a removal of these phenomena:

- Clean the material's surface with the BRUXSAFOL surface cleaner (article no. T21012) in order to remove the blushing formation.
- Heating the film with the help of a hot air gun (article no. T26006) or an IR heater (article no. T25910)
Low temperatures are already sufficient for the removal of blushings; marks in the film disappear at medium temperatures.
- If these two measures are not sufficient to remove the phenomena, please use the PWF CARE Carnauba Wax (article no. T22621) and apply the wax on the film surface.
Follow the instructions on the product packaging.

If you have any questions, please contact our sales team.



„End of Roll“ - mark on the film before treatment



„Blushing“ - storage stains before treatment